

CONFIDENTIAL

P 272149Z  
 FM NPIC WASHDC  
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB  
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
 RUCVAA/2D RTS BARKSDALE AFB LA  
 RUEAHQ/DIA WASHDC  
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD  
 RUEPIA/CIA WASHDC  
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF  
 RUWGAA/2AF BARKSDALE AFB LA  
 BT  
 SECRET CITE NPIC 3153

1964 OCT 27 22 14Z

OUT54322

28 OCT 1964

HFS *[Signature]*

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 15 WAS USED IN MISSION 3958 FLOWN ON 26 OCTOBER 1964.  
 PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: STATIC SPOTS ARE NOTED ADJACENT TO THE INBOARD EDGE OF THE FILM THROUGHOUT AND ADJACENT TO THE OUTBOARD EDGE OF THE FILM ON THE FIRST 140 FRAMES OF THE MISSION. THESE SPOTS ARE POSSIBLY ASSOCIATED WITH THE PRESSURE ROLLER. A PLUS DENSITY STREAK IS PRESENT 3.31" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM THROUGHOUT. EDGE FOG IS PRESENT INTERMITTENTLY ALONG THE OUTBOARD EDGE OF THE FILM. IRREGULAR PLUS DENSITY TRACES ARE NOTED NEAR THE INBOARD EDGE OF THE FILM ON FRAMES 379, 380 AND INTERMITTENTLY ON FRAMES 495 THROUGH 530. A HEAT SPLICE IS MADE IN FRAME 583 WITH ASSOCIATED PLUS DENSITY TRACES AND CRIMPS ON FRAMES 578, 582 AND 583. METERING VARIED FROM 0.3" TO 0.5" IN WIDTH.

C. 9L SIDE: METERING VARIED FROM 0.25" TO 0.81" IN WIDTH.

Grace (File)

-2-

FRAME 002 CONTAINS NUMEROUS PINHOLES. A MANUFACTURER'S SPLICE IS MADE IN FRAME 37 WITH ASSOCIATED STATIC TRACES ON FRAMES 36, 37 AND 38. A HEAT SPLICE IS MADE IN FRAME 644 WITH ASSOCIATED STATIC TRACES AND CRIMPS ON FRAMES 642 AND 643.

D. BOTH SIDES: EDGE STATIC OCCURS INTERMITTENTLY ALONG BOTH FILM EDGES THROUGHOUT THE MISSION. SMEARED IMAGES ARE NOTED ON SEVERAL FRAMES. THIS SMEARING APPEARS TO BE ROLL ORIENTATED AND POSSIBLY ASSOCIATED WITH NECESSARY TURN MANEUVERS. FRAMES ARE TITLED CONSECUTIVELY FROM 001 THROUGH 1076.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED DURING THE MISSION.

3. POSITIVES:

A. FI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 25 PERCENT OF THE MISSION.

S E C R E T

--END OF MESSAGE--